

Informacije o oznakama guma

U vezi s informacijama, koje se odnose na odredbu označavanja guma za putnička vozila, koja je stupila na snagu od 1. maja 2021 (EC, br. 2020/740), molimo vas da pogledate donje informacije.

Vozilo

Oznake guma

Ime	Dimenzija naplataka	Proizvođač guma	Dimenzija guma	Potrošnja goriva	Prianjanje na mokroj podlozi	Buka	
				Razred	Razred	Nivo buke	Rezultat (dB)
KORANDO	17	Kumho	225/60R17 99H	C	C	B	70
KORANDO	18	Kumho	235/55R18 100H	C	B	B	71
KORANDO	19	Kumho	235/50R19 99H	C	C	B	71
KORANDO	18	Hankook	235/55R18 100H	C	B	B	70
KORANDO	19	Hankook	235/50R19 99H	C	C	B	69
KORANDO	17	NEXENTIRE	225/60R17 99H	C	C	B	71
KORANDO	19	NEXENTIRE	235/50R19 99H	C	C	B	70
TORRES	17	Kumho	225/60 R17 99H	B	C	B	71
TORRES	18	Hankook	235/55R18 100H	C	C	B	70
TORRES	18	NEXENTIRE	235/55R18 100H	B	C	C	71
TORRES	20	Hankook	245/45R20 99V	B	C	B	67
TORRES	20	NEXENTIRE	245/45R20 99V	A	C	B	71
TIVOLI	16	Kumho	205/60R16 92H	B	C	B	70
TIVOLI	16	Kumho	205/65R16 95H	C	C	B	69
TIVOLI	16	NEXENTIRE	205/65R16 95H	C	C	B	70
TIVOLI	18	Kumho	215/50 R18 92H	C	B	B	71
TIVOLI	18	Kumho	215/50 R18 92H	C	C	B	71
TIVOLI	18	Hankook	215/50 R18 92H	C	B	B	70
TIVOLI	18	Nexen	215/50 R18 92H	C	C	B	71
REXTON	17	KUMHO	235/70R17 107H	B	C	B	71
REXTON	18	KUMHO	255/60R18 108H	B	C	B	72
REXTON	18	NEXENTIRE	255/60R18 108H	B	C	A	69
REXTON	20	KUMHO	255/50R20 105H	B	C	B	72
REXTON	20	Hankook	255/50R20 105H	B	C	B	71
REXTON	20	NEXENTIRE	255/50R20 105H	B	C	B	70
REXTON	18	Michelin	255/60R18 112W	C	A	B	72
REXTON	18	Kumho	255/60R18 112V	C	B	B	72
MUSSO	17	KUMHO	235/70R17 107H	C	C	B	71
MUSSO	18	NEXENTIRE	225/60R18 108H	C	B	B	71
MUSSO	18	KUMHO	225/60R18 108H	C	C	B	71
MUSSO	20	NEXENTIRE	225/50R20 105H	C	C	B	71
MUSSO	20	Hankook	225/50R20 105H	C	C	B	70
MUSSO	20	Kumho	225/50R20 105H	C	C	B	72
MUSSO	17	Nexen	235/70R17 111T	C	C	B	72
TORRES EVX	18	Nexen	225/60R18 100H	A	C	B	71
TORRES EVX	20	Nexen	245/45R20 99V	B	C	B	70

1) Potrošnja goriva

Gume s manjim otporom trenja smanjuju potrošnju

2) Prianjanje na mokroj podlozi

Prianjanje na mokroj podlozi je od ključnog značaja

3) Buka

Radi se o vanjskoj buci, koju prouzrokuju